	:		
		2 September 1971	•
		II C Corrown and	
		U. S. Government	
		Gentlemen:	07
		Reference: Contract	ST
	:	In reference to the above contract, has incurred additional standby time at the installation site during the period of August 22, 1971 through	S1
	*	August 29, 1971. This standby time is caused by the room environment	
		not meeting specifications is attempting to work and progress with the installation in every area possible.	
		The lost time by personnel for the period of August 22, 1971, through August 29, 1971, is as follows:	
		August 23 8 hours	
		August 24 27 hours August 25 16 hours	
		August 26 27 hours August 27 8 hours	
		Total Time Involved 86 hours	
		Total Per Diem days lost 8	
:		The detailed cost of this period of time, August 22, 1971, through	
		August 29, 1971, is as follows:	
			•
:			
1			
:			
	a source		

Approved For Release 2003/12/04 : CIA-RDP78B05171A000100010026-0

Declass Review by NIMA/DOD

STAT

## Approved For lease 2003/12/04 : CIA-RDP78B0517 000100010026-0

U.S. Government 2 September 1971 Page 2

management and technical personnel are available to furnish any additional information you might require.

Very truly yours,

Director of Hamming

BCJ/lab

STAT

STAT

In reference to the above contract, has incurred additional standby time at the installation site during the period of August 9, 1971 through August 21, 1971. This standby time is caused by the room environment not meeting specifications. is attempting to work and progress with the installation in every area possible, and we are most anxious to complete our work at the site.
TAT Reference: Contract No.  In reference to the above contract, has incurred additional standby time at the installation site during the period of August 9, 1971 through August 21, 1971. This standby time is caused by the room environment not meeting specifications. his attempting to work and progress with the installation in every area possible, and we are most anxious to complete our work at the site.  TAT The lost time by personnel by day is as follows:  August 9  August 10  August 10  August 11  August 12  August 13  28 hours  August 13
In reference to the above contract, has incurred additional standby time at the installation site during the period of August 9, 1971 through August 21, 1971. This standby time is caused by the room environment not meeting specifications. Is attempting to work and progress with the installation in every area possible, and we are most anxious to complete our work at the site.  AT The lost time by personnel by day is as follows:  August 9  August 10  August 10  August 11  August 12  August 12  August 13  28 hours  August 13
at the installation site during the period of August 9, 1971 through August 21, 1971. This standby time is caused by the room environment not meeting specifications. Is attempting to work and progress with the installation in every area possible, and we are most anxious to complete our work at the site.  AT The lost time by personnel by day is as follows:  August 9  August 10  August 11  August 11  August 12  August 12  August 13  28 hours
August 9 August 10 August 11 August 11 August 12 August 13
August 10 August 11 August 11 August 12 August 13 August 13 22 hours 32 hours 28 hours
August 17 51 hours August 18 38 hours August 19 24 hours August 20 24 hours August 21 8 hours Total time involved 301 hours
Total Per Diem days lost 53

Approved For Release 2003/12/04 : CIA-RDP78B05171A000100010026-0

## Approved For Refease 2003/12/04 : CIA-RDP78B05171A000100010026-0

U.S. Government 24 August 1971 Page 2

Kindly note that the foregoing standby time is subsequent to the time summarized in our letter of August 13, 1971.

**STAT** 

management and technical personnel are available to furnish any additional information you might require.

Very truly yours,

**STAT** 

Vice President

WJW:mt